
#19

STRUCTURAL CORNER CONNECTION



NOTE: ALL RED DOTS - APPLY CONTINUOUS $\frac{3}{8}$ " DIA. BEAD OF MASTIC SEALANT AT WOOD TO FOAM \$ WOOD TO WOOD CONNECTIONS AT INTERIOR SIDE.

DETAILS ARE TYPICAL OF STANDARD CONDITIONS AND MAY NOT APPLY TO ALL PROJECTS. REFER TO FINAL PROJECT APPROVAL DRAWINGS FOR SPECIFICATIONS. PLEASE CONTACT FPI TECHNICAL DEPARTMENT FOR QUESTIONS AND/OR CONCERNS.

STRUCTURAL CORNER CONNECTION DETAIL

SCALE: | " = | '-0"





WWW.FOARDPANEL.COM (800) - 644 - 8885